

SUTTER BYPASS Fact Sheet

PL84-99 Sites

Emergency Levee Repairs

Location

Watercourse: Sutter Bypass Site Identification #: 20051230-008-001 (Levee Mile 18.25)

Latitude/Longitude:

38.987050/-121.725600

Nearest Impact Area:

Robbins
County: Sutter
Bank: Left

Type of Damage

Bank erosion

Total Length of Repair


400 feet (approximate)

Repair Type

Relief wells, lined canal

Lead Agency

Reclamation District 1500



For further information, please contact:

Les Schmittner Project Manager U.S. Army Corps of Engineers (916) 440-2263

Lester.C.Schmittner@spk01.usace.army.mil

